

ROTAX-OWNER.COM

Engine and Crankshaft serial numbers affected by Alert Service Bulletin ASB-912-059 / 914-042

This list prepared by Rotax Owner on November 16th, 2011.

This list is intended as supplementary information and does not supercede the information in the above mentioned Alert Service Bulletin.
The information provided in the Alert Service Bulletin in authoritative.

Engines produced with crankshafts affected by ASB-912-059 / 914-042		
ENGINE TYPE	ENGINE SERIAL #	CRANKSHAFT SERIAL #
912 A2	4410884	40426
912 A2	4410885	40424
912 A3	4410886	40423
912 A3	4410887	40422
912 F3	4412984	40463
912 F3	4412985	40462
914 F2	4420965	40236
914 F2	4420966	40349
914 F3	4420967	40478
914 F3	4420968	40477
914 F2	4420969	40469
914 F2	4420970	40464
914 F2	4420972	40432
914 F2	4420973	40435
914 F2	4420974	40436
914 F2	4420975	40440
914 F2	4420976	40438
914 F2	4420977	40466
914 F2	4420978	40439
912 S3	4924044	40256
912 S3	4924045	40257
912 S3	4924046	40259
912 S3	4924047	40264
912 S3	4924048	40265
912 S3	4924049	40267
912 S2	4924050	40329
912 S2	4924051	40337
912 S3	4924052	40335
912 S3	4924053	40310
912 S2	4924054	40300
912 S2	4924056	40302
912 S2	4924058	40303
912 S2	4924064	40461
912 S2	4924065	40456
912 S2	4924066	40455
912 S2	4924067	40453
912 S2	4924068	40450
912 S3	4924069	40445
912 S3	4924070	40447
912 S3	4924071	40446
912 S3	4924072	40444
912 S3	4924073	40443
912 S3	4924074	40442
912 S3	4924075	40441
912 S3	4924076	40507
912 S2	4924077	40480
912 S2	4924081	40358
912 S2	4924082	40359
912 S3	4924083	40373
912 S3	4924084	40488
912 S3	4924086	40361
912 UL2	6770159	40298
912 UL2	6770160	40294
912 UL2	6770161	40293
912 UL2	6770162	40323
912 UL2	6770163	40319
912 UL2	6770164	40460
912 UL2	6770165	40459
912 UL2	6770166	40458

Engines produced with crankshafts affected by ASB-912-059 / 914-042

ENGINE TYPE	ENGINE SERIAL #	CRANKSHAFT SERIAL #
912 UL2	6770168	40454
912 UL2	6770169	40452
912 UL2	6770170	40451
912 UL2	6770171	40448
912 UL2	6770172	40479
912 UL2	6770173	40476
912 UL2	6770174	40475
912 UL2	6770175	40474
912 UL2	6770176	40473
912 UL2	6770184	40366
914 UL-LB2	6774151	40304
914 UL-LB2	6774152	40306
914 UL-LB2	6774153	40301
914 UL-LB2	6774154	40305
914 UL-LB2	6774155	40299
914 UL-LB2	6774156	40316
914 UL-LB2	6774157	40309
914 UL-LB2	6774158	40314
914 UL-LB2	6774159	40308
914 UL-LB2	6774160	40307
914 UL-LB2	6774165	40295
914 UL-LB2	6774166	40251
914 UL-LB2	6774168	40325
914 UL-LB2	6774169	40336
914 UL-LB2	6774170	40333
914 UL-LB2	6774171	40332
914 UL2	6774176	40315
914 UL2	6774177	40339
914 UL2	6774178	40340
914 UL2	6774179	40342
914 UL2	6774180	40343
914 UL2	6774181	40345
914 UL2	6774182	40346
914 UL2	6774183	40347
914 UL-LB2	6774184	40250
914 UL-LB2	6774185	40351
914 UL-LB2	6774186	40296
914 UL-LB2	6774187	40352
914 UL-LB2	6774188	40312
914 UL-LB2	6774189	40311
914 UL-LB2	6774190	40326
914 UL-LB2	6774191	40322
914 UL-LB2	6774192	40327
914 UL-LB2	6774193	40334
914 UL-LB2	6774199	40421
914 UL-LB2	6774200	40419
914 UL-LB2	6774201	40417
914 UL-LB2	6774202	40414
914 UL-LB2	6774203	40418
914 UL-LB2	6774204	40415
914 UL-LB2	6774205	40413
914 UL-LB2	6774206	40412
914 UL-LB2	6774207	40408
914 UL-LB2	6774208	40409
914 UL2	6774209	40472
914 UL2	6774210	40468
914 UL2	6774211	40471
914 UL2	6774212	40467
914 UL2	6774213	40470
914 UL-LB2	6774220	40246
912 ULS2	6777492	40235
912 ULS2	6777493	40233
912 ULS2	6777494	40240
912 ULS2	6777495	40239
912 ULS2	6777496	40234
912 ULS2	6777497	40244
912 ULS2	6777498	40243
912 ULS2	6777499	40237

Engines produced with crankshafts affected by ASB-912-059 / 914-042

ENGINE TYPE	ENGINE SERIAL #	CRANKSHAFT SERIAL #
912 ULS2	6777500	40252
912 ULS2	6777501	40247
912 ULS2	6777502	40253
912 ULS2	6777503	40255
912 ULS2	6777504	40254
912 ULS2	6777505	40249
912 ULSFR2	6777514	40263
912 ULS2	6777526	40331
912 ULSFR2	6777527	40330
912 ULS2	6777528	40321
912 ULS2	6777529	40317
912 ULS2	6777530	40313
912 ULS2	6777531	40318
912 ULS2	6777532	40338
912 ULS2	6777533	40320
912 ULS2	6777534	40341
912 ULS2	6777535	40348
912 ULS2	6777536	40344
912 ULS2	6777537	40367
912 ULS2	6777538	40324
912 ULS2	6777539	40368
912 ULS2	6777540	40369
912 ULS2	6777541	40370
912 ULS2	6777542	40371
912 ULS2	6777544	40357
912 ULS2	6777545	40360
912 ULS2	6777546	40372
912 ULS2	6777547	40363
912 ULS2	6777563	40374
912 ULS2	6777564	40365
912 ULS2	6777565	40258
912 ULS2	6777566	40260
912 ULS2	6777567	40261
912 ULS2	6777568	40262
912 ULS2	6777569	40266
912 ULS2	6777576	40297
912 ULS2	6777577	40506
912 ULS2	6777578	40505
912 ULS2	6777579	40504
912 ULS2	6777580	40500
912 ULS2	6777581	40503
912 ULS2	6777582	40501
912 ULS2	6777583	40499
912 ULS2	6777584	40498
912 ULS2	6777585	40495
912 ULS2	6777586	40491
912 ULS2	6777587	40484
912 ULS2	6777588	40490
912 ULS2	6777589	40489
912 ULS2	6777590	40487
912 ULS2	6777591	40483
912 ULS2	6777592	40482
912 ULS2	6777593	40481
912 ULS2	6777594	40497
912 ULS2	6777596	40431
912 ULS2	6777609	40427
912 ULS2	6777610	40496
912 ULS2	6777624	40350
912 ULS2	6777625	40354
912 ULS2	6777626	40353
912 ULS2	6777627	40355
912 ULS2	6777628	40356
912 ULS2	6777630	40362
912 ULS2	6777631	40364
912 ULS2	6777634	40410
912 ULS2	6777635	40411
912 ULS2	6777636	40416

Engines produced with crankshafts affected by ASB-912-059 / 914-042		
ENGINE TYPE	ENGINE SERIAL #	CRANKSHAFT SERIAL #
912 ULS2	6777637	40420
912 ULS2	6777638	40492
912 ULS2	6777639	40425
912 ULS2	6777640	40493
912 ULS2	6777641	40494
912 ULS2	6777642	40502
912 ULS2	6777667	40328
912 ULS2	6777668	40485
912 ULS2	6777686	40465
912 ULS2	6777688	40449
912 ULS2	6777689	40437
912 ULS2	6777690	40433

Crankshafts provided in Overhaul kits affected by ASB-912-059 / 914-042		
ENGINE TYPE	O/H KIT SERIAL #	CRANKSHAFT SERIAL #
912/914	9999673	40245
912/914	9999674	40242
912/914	9999675	40232
912/914	9999676	40248
912/914	9999677	40238
912/914	9999678	40241

Crankshafts provided as spare parts affected by ASB-912-059 / 914-042	
CRANKSHAFT SERIAL #	
40486	
40428	
40429	
40430	